

6 Emery Avenue Randolph, NJ 07869-1362 Telephone: 973-328-6611 Fax: 973-328-6935

www.killam.com

March 27, 1998

Fletcher N. Platt, Jr., P.E. Executive Vice President

Mr. Paul Harvey
Case Manager
New Jersey Department of Environmental Protection
Bureau of Federal Case Management
401 East State Street, 5th Floor, P. O. Box 028
Trenton, New Jersey 08625-0028

Re: Groundwater Recovery System Performance Report - November 1997

Madison Industries, Inc.

Dear Mr. Harvey:

We have recently received a copy of the above referenced report and wish to make the following comments on behalf of the City of Perth Amboy. On page 2 of the report in the third paragraph, the following is stated:

"This on-site ditch (Pricketts Brook) appears to act as both a groundwater discharge and recharge mechanism on the Madison site and is mostly dry, except during rainfall episodes when upland runoff contributes to flow within the ditch. Surface water is usually evident at the ditch's lowest elevation on the Madison site, in the vicinity of the Madison/Perth Amboy property fence.

Madison collected surface water samples from the on-site ditch approximately once or twice per month for the duration of the performance test when there was little or no rainfall. The samples were identified as D-1, D-2, and D-3. Sample D-1 was collected just west of the bridge, D-2 was collected in the vicinity of RW-3, and D-3 was collected at the fence. The results of this sampling exercise are provided on Table 2. Concentrations of zinc in the D-1, D-2, and D-3 samples ranged from 0.2 mg/l to 3.5 mg/l, 1.6 mg/l to 34.3 mg/l, 5.9 mg/l to 33.9 mg/l, respectively. Figure 8 provides a graphical representation of this data."

This data indicates that all samples collected at the Madison Industry/Perth Amboy fence line exceeded the water quality standards of 5 mg/l. The water sampled at this location flows down stream onto the City of Perth Amboy Runyon Watershed where waters from the brook recharge the aquifers from which the City's wells draw the water supply. This sampling exercise conducted by Madison Industries from March, 1997 through December, 1997 confirms that the heavy metals contamination on the Madison Industries' site is neither contained nor controlled.

Why hasn't NJDEP taken any action with regard to this continuing release?

[™] Killam

Mr. Paul Harvey Page 2 March 27, 1998

Both sampling locations D-2 and D-3 in Pricketts Brook are along side two potential sources for the heavy metals release. The area immediately along the northern side of Pricketts Brook is the location where for years Madison Industries stored in outside open piles materials containing high concentrations of zinc. The piles have been removed but it is suspected that residuals from this heavy metals pile are in the soils beneath this area.

The second potential source for this contamination in Pricketts Brook is the surface water retention basin immediately along the southern bank of Pricketts Brook near the fence line. This surface water retention basin receives runoff from the macadam surface of Madison Industries where historically, solid and liquid materials containing high concentrations of heavy metals have been released.

We request that NJDEP direct Madison Industries to investigate and identify the source of the heavy metals entering Pricketts Brook which are being discharged on to the City of Perth Amboy property.

The Madison Industries' Groundwater Recovery System Performance Report only presents analyses of zinc concentrations. There are three (3) other metals of concern identified on the Madison Industries' site (cadmium, copper and lead) which should also be sampled and analyzed. We believe that there may be different releases and/or sources contributing to the contamination plume of the various metals.

We request that you respond to these concerns and advise the City of Perth Amboy when NJDEP will take action against Madison Industries to provide for the containment and control for the contamination on their site. Should you wish to discuss this matter in further detail, do not hesitate to contact us.

Very truly yours,

KILLAM ASSOCIATES

Fletcher N. Platt, Jr., P.E.

enc.: cc: Letter December 31, 1997 Mayor Joseph Vas Louis Perez-Jimenez Leah Healey, Esq. John Osolin, USEPA Charles Licata. Esq.

N:\Projects\206020\Letters\L.206020i.wpd

C-97-12-01



December 31, 1997

Mr. Paul Harvey
Case Manager
New Jersey Department of Environmental Protection
Bureau of Federal Case Management
401 East State Street, 5th Floor, P.O. Box 028
Trenton, NJ 08625-0028

RE:

Groundwater Recovery System Performance Report - November 1997

Madison Industries, Inc.

Dear Mr. Harvey:

This letter report provides a summary of groundwater system performance for November 1997. This report is the last of six monthly reports prepared by Madison Industries, Inc. (Madison) for this phase of the shallow groundwater interim remedial action approved by the New Jersey Department of Environmental Protection (Department) in May 1997. This report also provides a summary of system performance for the entire test period, June 1997 through November 1997, as well as conclusions and recommendations pertaining to the shallow groundwater recovery system (RS-1) and other recovery wells on the Madison site.

Table 1 provides a summary of monitoring locations and groundwater level elevations for May 27, 1997 through November 24, 1997. Figure 1 provides a groundwater level contour map for the data obtained on November 24, 1997. This contour map was produced using geostatistical software and best professional judgement; some locations and detail are approximate. As shown, the capture zone of RS-1 is estimated to extend approximately 130 to 150 feet down gradient of RS-1 and provides groundwater control over the area that was suspected to contain elevated levels of zinc in groundwater. Despite minor fluctuations in groundwater level elevations on site during the performance test period, the capture zone of RS-1 and its influence on the direction of groundwater flow in the area of the recovery system has not varied significantly. It should be noted that, with the Department's authorization, RW-4 and RW-6 were inactive for the duration of the performance test.

Table 2 provides a summary of zinc concentrations, in milligrams per liter (mg/l), for the period of February 12, 1997 through December 3, 1997. As shown on the table, the average concentration of zinc from RS-1 on December 3 was 126.0 mg/l; this value is the lowest recorded zinc concentration since monitoring began in February. Concentrations of zinc ranged from 17.0 mg/l in RS-1C to 257.0 mg/l in RS-1A, and the concentration of zinc in down gradient monitoring well MI-9 was 2.67 mg/l on November 24. It is important to note that the average zinc concentration in RS-1 was as high as 1,195 mg/l on February 17, 1997 and that average zinc concentrations have decreased by more than 89 percent during the performance test period. Zinc concentrations, once as high as 1,860 mg/l in RS-1C, have decreased 99 percent to a low of 17.0 mg/l. The average concentration of zinc in RS-1 continues a downward trend despite several fluctuations; Figure 2

provides a graphical representation of the average zinc concentration data and linear regression trend line since February 1997. Figure 3 provides a graphical representation of zinc concentration data for RS-1A and RS-1B for the same period. As shown on Figure 3, zinc concentrations in RS-1A and RS-1B continued to decrease rapidly until late July 1997. From that period forward, zinc concentrations continued to decrease at a lesser rate and have generally been below 400.0 mg/l. Figure 4 provides a graphical representation of zinc concentrations data for RS-1A and RS-1B for the period of July 1, 1997 through December 3, 1997. Figure 5 provides a graphical representation of zinc concentration data for RS-1C and RS-1D since February 1997. Zinc concentrations in RS-1C and RS-1D decreased rapidly until mid April 1997 and then also continued to decrease at a lesser rate, but have remained generally below 100.0 mg/l. Figure 6 provides a graphical representation of zinc concentration data for RS-1C and RS-1D for the period of July 1, 1997 through December 3, 1997. As previously mentioned, concentrations of zinc in RS-1C and RS-1D were 17.0 mg/l and 66.0 mg/l, respectively, on December 3, 1997.

Table 3 provides a summary of zinc concentrations for selected wells on and in the vicinity of the Madison site for the 12 Performance Monitoring Periods (PMPs) from December 1994 through September 1997. These wells include: MI-2A, MI-7, MI-9, MI-T1, RS-1, RW-4, and RW-6 on the Madison site; and RW-2, WCC-11M, WCC-12, WCC-15M, and WCC-16VS located on the Perth Amboy watershed property. Figure 7 provides a graphical representation of zinc concentrations for three of the wells on and in the immediate vicinity of the Madison site -- RW-4, RW-6, and WCC-11M. As shown on Table 3 and Figure 7, there was a decrease in zinc concentrations in RW-4, RW-6, and WCC-11M beginning with the March 1997 PMP, one month after the startup of RS-1, and continuing through the September 1997 PMP. In fact, the concentrations of zinc in RW-4, RW-6, and WCC-11M, decreased 97 percent, 96 percent, and 96 percent, respectively, from the December 1996 PMP to the September 1997 PMP. Concentrations of zinc also decreased in MI-7, MI-T1, RW-2, and WCC-15M to a lesser degree.

Madison also collected and evaluated periodic surface water samples from the on-site ditch down gradient of RS-1 during this performance test period. The purpose of this effort was to determine if RS-1 would affect changes in zinc concentrations in surface water within the on-site ditch down gradient of the shallow recovery system. This on-site ditch appears to act as both a groundwater discharge and recharge mechanism on the Madison site and is mostly dry, except during rainfall episodes when upland runoff contributes to flow within the ditch. Surface water is usually evident at the ditch's lowest elevation on the Madison site, in the vicinity of the Madison/Perth Amboy property fence.

Madison collected surface water samples from the ditch approximately once or twice per month for the duration of the performance test when there was little or no rainfall. These samples were identified as D-1, D-2, and D-3. Sample D-1 was collected just west of the bridge, D-2 was collected in the vicinity of RW-3, and D-3 was collected at the fence. The results of this sampling exercise are provided on Table 2. Concentrations of zinc in the D-1, D-2, and D-3 samples ranged from 0.2 mg/l to 3.5 mg/l, 1.6 mg/l to 34.3 mg/l, 5.9 mg/l to 33.9 mg/l, respectively. Figure 8 provides a graphical representation of this data.

Additionally, Madison evaluated previous PMP data from December 1994 through September 1997. As shown on Table 3, concentrations of zinc in SW-2 (equivalent to sample location D-3) had been as high as 470.0 mg/l and 415.0 mg/l in June 1996 and September 1996, respectively. These samples were collected during periods of minimal precipitation with little or no flow in the ditch. During the same periods in 1997, the concentrations of zinc were 22.7 mg/l and 28.3 mg/l at D-3, again with little or no flow in the ditch. A comparison of these PMP results and the results of the ditch samples collected during the performance test indicates that RS-1 has a significant effect on the concentrations of zinc in the ditch. In fact, comparing the PMP results alone, there was a 95 percent and 93 percent reduction, respectively, in zinc concentrations between the samples

Mr. Paul Harvey December 31, 1997 – Page 3

collected in the June and September 1996 and the samples collected in June and September 1997. These reductions appear to be consistent with the reductions in zinc concentrations in RS-1 and the down gradient monitoring points. As previously discussed zinc concentrations as low as 5.9 mg/l have been recorded at the D-3 sample location.

In conclusion, zinc concentrations in RS-1 continue to decrease; however, more importantly, zinc concentrations in monitoring wells at and in the vicinity of the Madison site appear to be decreasing as well. It is Madison's opinion that the RS-1 performance test, with the approved exclusion of RW-4 and RW-6, was successful and that RS-1 continues to be effectively and efficiently removing elevated levels of zinc from the Old Bridge Aquifer. Additionally, RS-1 appears to have a significant influence over the concentrations of zinc in the surface water in the on-site ditch, despite flow or upland runoff conditions.

Therefore, Madison recommends that RW-4 and RW-6 remain inactive indefinitely. Although RW-4 and RW-6 may have influenced groundwater flow at and in the vicinity of the site at some point, both wells lacked zinc-recovery efficiency because of well depth and/or high pump capacity. Madison also proposes to eliminate the use of RS-1C, because of its relatively low zinc concentrations, allowing the remaining three wells, RS-1A, RS-1B, and RS-1D to remove zinc more efficiently. Madison may propose to eliminate RS-1D at some future point in time. Madison further proposes to monitor the performance of RS-1, including the down gradient monitoring well MI-9 and surface water at the D-3 location, on a monthly basis and incorporate the results and findings with the quarterly PMP reports.

If you have any questions regarding this report, please do not hesitate to contact either Frank Holloway or me.

Sincerely,

MADISON INDUSTRIES, INC.

Barry J. Vroeginday, CPG

Director, Site Remediation

Enclosure

cc:

Bruce Bzura, Madison Industries (w/enc.)
Susan Gieser, Esq., Madison Industries (w/enc.)
Frank Holloway, Madison Industries (w/enc.)
John Osolin, USEPA (w/enc.)
Lawrence Pollex, City of Perth Amboy (w/enc.)

TABLE 1
SUMMARY OF MONITORING LOCATIONS
AND GROUNDWATER LEVEL ELEVATIONS(1)
GROUNDWATER RECOVERY SYSTEM PERFORMANCE REPORT - NOVEMBER 1997
MADISON INDUSTRIES, INC.

WELL/	WELL	WELL/				GROU	NDWATER ELEV	ATION					
LOCATION	DEPTH	LOCATION	27-May-97	28-May-97	29-May-97	16-18-May-97	31~Jul-97	29-Aug-97	30-Sep-97	28-Oct-97	24-Nov-97		
NUMBER	(S/D)	ELEVATION	 	NA NA	NA	NA NA	NA	NA	NA	NA	NA		
CPS-1	NA .	NA NA	NA		16.65	16.53	16.77	16.33	15.99	15.80	16.19		
VI-2A	s	22.09	16.63	16.64		18.57	18.88	18.47	18.10	17.21	18.30		
VI-3	S	22.77	17.50	18.78	18.82	21.85	22.05	21.62	20.89	20.57	21.24		
MI-4	S	24.17	21.97	22.02	22.03		23.14	22.70	22.02	21.83	22.39		
MI-5	S	25.25	23.18	22.40	22.41	22.95	21.63	17.56	20.50	20.20	20.77		
MI-6	D_	26.48	21.43	21.61	21.55	21.51	18.37	17.76	17.28	17.08	17.66		
MI-7	S	23.80	18.29	18.37	18.35	18.03	18.98	18.55	18.22	18.06	18.44		
MI-8	s	25.15	17.87	18.88	18.88	18.69		18.59	18.12	17.88	18.39		
MI-9	S	25.69	18.74	18.28	18.92	18.75	19.09	17.53	17.03	18.92	17.24		
MI-T1	S	23.79	17.94	17.93	17.93	17.74	18.06	16.23	15.86	15.41	15.84		
RS-1A	S	24.99	15.94	15.95	15.94	16.28	18.82		15.72	15.32	15.87		
RS-1B	S	25.08	15.97	15.94	15.92	16.39	16.68	16.26	16.50	16.21	16.70		
RS-1C	S	25.10	16.84	16.87	16.85	17.10	17.34	17.00	15.50	15.20	13.71		
RS-1D	S	25.12	15.87	16.44	16.37	15.97	15.82	17.60	18.63	18.04	18.88		
RW-3	D	24.89	19.21	19.57	19.46	19.36	19.63	18.70		18.27	18.69		
RW-4	D	23.93	-12.48	19.08	19.07	19.04	18.53	19.38	18.46	15.92	16.30		
RW-6	S	21.47	16.48	16.66	16.65	16.50	16.67	16.37	16.07	19.64	18.40		
WFH-3	S	27.53	19.63	19.84	19.22	18.67	19.23	19.15	18.00	17.49	17.97		
X-1	S	22.82	18.29	18.59	18.61	18.32	18.62	18.13	17.67		17.87		
X-2	S	23.12	18.14	18.48	18.50	18.18	18.57	18.06	17.60	17.42	17.38		
X-3	S	24.43	18.37	18.87	18.90	18.71	18.95	18.48	18.03	17.82	16.83		
X-4	S	23.09	17.85	18.63	18.66	17.45	18.71	18.27	17.89	17.71	18.14		
X-5	s	23.41	17.43	18.59	18.63	18.46	18.71	18.31	17.95	17.79			
X-6	s	18.69	13.90	13,92	13.93	13.73	14.41	13.57	13.15	14.01	13.37		
	- s	18.76	14,68	14.88	14.83	14.50	15.16	13.71	14.03	13.04	13.29		
X-7 MI-SG	NA NA	25.70	19.24	19.26	19.14	19.13	19.06	18.50	18.00	18.25	NA NA		

NOTES:

- S Designated as a shallow well (< 40 feet in depth)
- D Designated as a deep well (> 40 feet in depth)
- (1) All elevations in feet above/below Mean Sea Level (MSL)
- NA Not available/applicable

TABLE 2
SUMMARY OF ZINC CONCENTRATIONS (MG/L)
GROUNDWATER RECOVERY SYSTEM PERFORMANCE REPORT - NOVEMBER 1997
MADISON INDUSTRIES, INC.

DATE		RECOVER	Y SYSTE	w wells		WATER TREAT.		ONITORII RVATION		SURFACE WATER			
SAMPLED	RS-1A	RS-1B	RS-1C	RS-10	AVG.	COMP.	X-8	X-7	MI-9	D-1	D-2	D-3	
2/12/97	750	1000	1860	1150	1190	990	1500	1210	1040.00	0.8			
2/13/97	740	980	1350	950	1005								
2/14/97	1070	1630	1810	1210	1430				890.00				
2/15/97	NA	NA	NA	NA	NA								
2/17/97	1010	1540	1570	660	1195								
2/18/97	1020	1460	1320	670	1118		-		740.00				
2/19/97	880	1310	1240	620	1013								
2/20/97	1130	1390	1270	730	1130								
2/21/97	1090	1330	1110	486	1004	1095			423.00				
2/22/97	NA	NA	NA	NA	NA	1005							
2/24/97	1080	1520	980	530	1028								
2/25/97	1140		870	660	975				690.00				
2/26/97	910	 	820	650	848								
2/27/97	1290		730	480	935						T		
2/28/97	870	 	570	220	693				226.00				
3/01/97	NA			NA	NA				,				
3/03/97	840		780	590	810								
3/04/97	1000			332	731				212.00				
3/05/97	850			410	668								
3/05/97	790		}		693								
3/07/97	790			 	633				84.00			<u> </u>	
3/07/97	NA NA				NA	+		 			<u> </u>		
	660			281	596		!			-	 		
3/10/97	870			246				107	102.00	0.6	1.6	25.0	
3/11/97	690		 	}				107	102.50				
	770		-					<u> </u>	<u> </u>		 	 	
3/13/97	880						. 		61 00		 		
3/15/97	880		 		i			<u> </u>	1			<u> </u>	
3/17/97	680	 		ļ		+		 				 	
							 	<u> </u>	!		+	-	
3/18/97	890	+	+	}			}		<u> </u>	 	+	-	
3/19/97			+	+				 		1	+	 	
3/20/97	930							 	46.80	1	 		
3/21/97	890				!			 		1	 	1	
3/22/97	N/ 810				 			+	<u> </u>	 	1	1	
3/24/97	+		+		 		-	 	34.70	1	 	 	
3/25/97	810				+			-	1 37.70	-	- 	 	
3/26/97	870			+	;	_		 	 	+	-	 	
3/27/97	790		+						 	 	-	-	
3/28/97	N/						†	1	<u> </u>	1		-	
3/31/97	810		+	 				 	22.00	1	-	-	
4/1/97	880							 	32.90	1	+		
4/2/97	810				+			1	 	 	-	+	
4/3/97	970			+				-			 	-	
4/4/97	830				+			1	58.00	' 	-	.	
4/5/97	N/	_}			+			 		 	 	-	
4/7/97	640									<u> </u>	<u> </u>	 	
4/8/97	100							<u> </u>	1		+	-	
4/9/97	89	0 970	208	3 212	57	0 565	5]	<u> </u>	84.00	<u> </u>	<u> </u>		

TABLE 2
SUMMARY OF ZINC CONCENTRATIONS (MG/L)
GROUNDWATER RECOVERY SYSTEM PERFORMANCE REPORT - NOVEMBER 1997
MADISON INDUSTRIES, INC.

						WATER TREAT.		ONITORI RVATION	11 9 39 3 5 5 5 5 6 6 6 6	SURFACE WATER			
DATE			Y SYSTE		AVG.	COMP.	X-8	X-7	MI-9	D-1	D-2	D-3	
SAMPLED	RS-1A	RS-1B	RS-1C	RS-1D 243	483	483	20000 4.70. 20000						
4/10/97	690	800	197	298	564	515			60.00				
4/11/97	730	960	268		NA	507							
4/12/97	NA	NA	NA 105	NA 222	514	499							
4/14/97	680	960	195		631	552		 	61.00	0.6	34.3	9.4	
4/15/97	830	820	NA	244	501	424		 					
4/16/97	790	950	113	152	469	-		+					
4/17/97	690	840	151	196	452			 	35.50				
4/18/97	690	830		170	586	-		 					
4/21/97	870	1030		231	603			 	48.20				
4/22/97	800	960		381									
4/23/97	NA	1050		370	571			+					
4/24/97	NA NA	1040		309					41.50				
4/25/97	NA	1420		298					1115				
4/26/97	409					+	+			1			
4/28/97	970								16.50	<u></u>	<u> </u>		
4/29/97	790				+	<u> </u>		- 	10.00				
4/30/97	920								 	 	1		
5/1/97	840								28.30	1			
5/2/97	680				+				25.50	+	 		
5/3/97	N/			+	+			_	 	+			
5/5/97	800								38.70	<u>- </u>			
5/6/97	1180			+				 -	30.7		+	1	
5/7/97	800								 		-	-	
5/8/97	64(70			 -				46.0			+	
5/9/97	1100								40.0		+	1	
5/10/97	N/											+	
5/12/97	83								29.0				
5/13/97	112					-i	_		23.0	0.	4 11.	0 10.7	
5/14/97	98							_		 	7		
5/15/97	94								22.7				
5/16/97	94	0 100		_+					22.1				
5/17/97	N,					A 33							
5/19/97	72	_		5 14					111.0				
5/20/97	28					7 34		_	111.0				
5/21/97	94					30 47			17.4				
5/22/97						19 33			33.2				
5/23/97	73					3 36			33.4	201			
5/24/97	N		A N			IA 54	_	_	100	0 0	.2 11	5 5.9	
5/27/97	97					73 40			18.8	0			
5/28/97	107						8	_				_	
5/29/97			20 17				20			-0			
5/30/97	73	30 84	10 14				9		22.1	(0)			
5/31/97	N				_		17						
6/1/97	N	IA N			_		24						
5/2/97	85	50 9	10 12				75			-			
6/3/97	7.	40 8	10 13				20		13.	40	_		
6/4/97	6:	30 7	20 1				81				_		
6/5/97	5-	49 5	50	30 1	33 3	31 3	04						

TABLE 2
SUMMARY OF ZINC CONCENTRATIONS (MG/L)
GROUNDWATER RECOVERY SYSTEM PERFORMANCE REPORT - NOVEMBER 1997
MADISON INDUSTRIES, INC.

				AND NO		WATER		NONITORI		SURFACE WATER			
DATE		RECOVER		RS-1D	AVG.	COMP.	X-8	X-7	MI-9	0-1	D-2	D-3	
SAMPLED	RS-1A	RS-1B	RS-1C	123	405	167	and the second	3000-4.3.00	10.30				
6/6/97	760	640	98	NA	NA NA	167							
6/7/97	NA	NA	NA NA	NA	NA NA	298							
6/8/97	NA	NA	94	134	377	320		 		0,95	10.8	20.9	
6/9/97	590	690	75	136	333			 	9.70				
6/10/97	520	600	89	117	359								
6/11/97	590	640	83	124	347			 					
6/12/97	570		101	145	389			 	10.40				
6/13/97	650	660		NA NA	NA			 					
6/14/97	NA NA		NA	NA NA	NA NA			 					
6/15/97	ÑΑ		NA 84		339		 		 				
6/16/97	590			123				 	 				
6/17/97	590			119	366			+	9.00				
6/18/97	488				299				- 0.00	-			
6/19/97	560		-		339				7.00				
6/20/97	560		+	}	342			+	1.00	 			
6/21/97	NA NA		 		N/				 	 			
6/22/97	NA NA									1.2	12.8	24.4	
6/23/97	437							 	7.10				
6/24/97	660			!					1 7.10				
6/25/97	640									-		 	
6/26/97	840								8.00	\			
6/27/97	310								1 0.50	1			
6/28/97	N/						+	- 					
6/29/97	I NA	 -			`					1			
6/30/97	370							- 	13.10	1		1	
7/1/97	41							- 	13.1	71			
7/2/97	54									 			
7/3/97	49		+										
7/4/97	l N											 	
7/5/97	N,							_			-		
7/6/97	N.						<u> </u>				 	<u> </u>	
7/7/97	56						5		9.4			 	
7/8/97	83							-	3.4			 	
7/9/97	40				_				+		 		
7/10/97	54				_	7 18		 -	8.2		 		
7/11/97	70								- 0.2	-	 	 	
7/12/97	l N								-		 	 	
7/13/97		A N				A 15			-		1	-	
7/14/97	39								8.9		+	+	
7/15/97	23					74 17	_		0.8		 		
7/16/97	45			5 11									
7/17/97	33					32 30						+	
7/18/97	29					99 19			7.8	101	+	- 	
7/19/97			A N			IA 21					 	 	
7/20/97			A N			JA 50	_		_	3.5	30.	1 33.9	
7/21/97				2 10		51 43		-	- - - - - - - - - - 		30	33,8	
7/22/97		38 37				19 22			4.5	100	+	- 	
7/23/97	40	04 44	14 7	4 8	8 2	53 19)4				<u> </u>	_	

TABLE 2 SUMMARY OF ZINC CONCENTRATIONS (MG/L) GROUNDWATER RECOVERY SYSTEM PERFORMANCE REPORT - NOVEMBER 1997 MADISON INDUSTRIES, INC.

						WATER TREAT.		MONITOR	 1 1 20 20 20 20 20 20 20 20 20 20 20 20 20		SURFA	CE:WAT	ER
DATE			Y SYSTE		***	COMP.	X-8	X-7	MI-9	D-	1 8	D-2	D-3
SAMPLED	RS-1A		RS-1C	RS-10	AVG.	220							
7/24/97	NA	367	NA	80	224 NA	NA		+	18.60				
7/25/97	NA	NA	NA	NA 75	190	241		 					
7/26/97	308	317	60	75	NA NA	189							
7/27/97	NA	NA	ŅA	NA NA	NA NA	107		 	<u> </u>				
7/28/97	NA	NA	NA	NA					5.40				
7/29/97	428	493	80	104	276			+	-				
7/30/97	NA	296	85	93	158			+	 				
7/31/97	NA	NA	NA	NA	NA				3.68				
8/1/97	274	288	87	99	187				0.00	-			
8/2/97	NA	ŊĄ		NA	NA NA		 		 	-			
8/3/97	NA	NA	NA	NA	N/A					-			
8/4/97	295	323	64	76	190				4.47	├			
8/5/97	341	337			208	+			4.47				
8/6/97	452	371	69		245		+			+-			
8/7/97	355	351	62		213			_	 	,	- 		-
8/8/97	304	286	56		18				4.78	-			1
8/9/97	NA.	NA	NA	NA NA	N/					┼			1
8/10/97	NA.	N/	NA NA	NA NA	N/	A NA	<u> </u>			-			
8/11/97	383	356	5 48	77	21	6 N/	1			 			-
8/12/97	345			85	21	3 N/	<u>\ </u>		4.5	11 .			
8/13/97	219			91	15	6 N/	<u> </u>			<u> </u>			
8/14/97	360			95	22	8 N	1			 			
8/15/97	338			92	21	3 N/	۹ ا		3.8	3			
8/16/97	370			90	21	8 N	۸ ا			1_			
8/17/97	N/				l N	Al N	4						
8/18/97	N/				l N	A N	٨						
8/19/97	45				28	9 N	A		4.8	6	1.4	7.	6 14.
8/20/97	39					4 N	A						
	39			_		3 N	A						
8/21/97	40						Αĺ		13.1	0			
8/22/97	N.		A N				A						
8/23/97					_		A			\neg			
8/24/97	N.		A N				A						
8/25/97	N		5 43.				A		2.9	13			
8/26/97	33			7 89						\neg			
8/27/97	31						A		- 	\dashv			
8/28/97	30						A A		3.2	27			
8/29/97	35						IA		- 	\top			1
8/30/97							IA						
8/31/97		 _		A N			IA		_	+			
9/1/97				A N					7	08			
9/2/97				32 7			IA			~			<u> </u>
9/3/97				9 8			IA			+			
9/4/97				IA N			JA						
9/5/97	2	76 3	50			_	IA		- 3 .	06			
9/6/97	1	IA N	IA N	IA N	A 1		VA	_		+			
9/7/97	1	IA N	IAI N	IA N			VA						
9/8/97			42	50 9	7 2		NA			\dashv		<u> </u>	
9/9/97				39 6	8 2	111	NA			_		<u></u>	

TABLE 2
SUMMARY OF ZINC CONCENTRATIONS (MG/L)
GROUNDWATER RECOVERY SYSTEM PERFORMANCE REPORT - NOVEMBER 1997
MADISON INDUSTRIES, INC.

						WATER		IONITORI RVATION		SURFACE WATER			
DATE		RECOVER				TREAT.	X-8	X-7	MI-9	0-1		D-Z	D-3
SAMPLED	RS-1A	RS-1B	RS-1C	RS-1D	AVG.	COMP.	A-0	A-10				<u> </u>	
9/10/97	395	393	48	80	229	NA NA					_		
9/11/97	348	398	49	71	217	NA NA		 	3.29		_		
9/12/97	345	350	38	70	201	NA			3.23		_		
9/13/97	NA	NA	NA	NA	NA	NA NA			 		一		
9/14/97	NA	NA	NA.	NA	NA.	NA					十		
9/15/97	358	352	42	72	206			 -	4.23		一十		
9/16/97	383	372		87	222		 	 	4.23		+		1
9/17/97	373	376			218			 	 		-		1
9/18/97	330	350		79	199	 		 	3.96		十		
9/19/97	314	343	37	70	191			 	3.30		-+		
9/20/97	NA	NA	NA		NA			 -	 	 	\dashv		-
9/21/97	NA	. NA	NA NA	NA	N/				ļ		-+		+
9/22/97	287	268	29	116	175			 	ļ		+		
9/23/97	341	320	37	71	192			 	1	 	+		-
9/24/97	320	235	26	74	164		+		4.66	<u> </u>	-+		
9/25/97	199	221	23	75	130			ļ	ļ				
9/26/97	238	219	24	75	139	el NA	1		<u> </u>	 	-+		
9/27/97	N/	+	N/	NA	N/	N/	1	<u> </u>	<u> </u>	<u> </u>	+		
9/28/97	N/		N/	NA NA	. N	À NA	1			 -			
9/29/97	l NA		A NA	NA NA	N/	A N	1			 			
9/30/97	333		3!	70	18	3 N	1		2.8	9			
10/1/97	385		41 4	110	23	5 N	<u> </u>			ᆜ			
10/2/97	31		0 3	3 65	18	3 N.	1			<u> </u>			
10/3/97	37		1 4	101	21	91 N.	4		3.6	71			
10/4/97	N/		Al N	AN A	N.	AL N	4	_!		<u> </u>			
10/5/97	N/	Al N	Al N	A NA	N.	A N	۸			 			
10/6/97	36		3 3	7 82	2 20	9 N	<u> </u>			_	NA	17	.2 18
10/7/97	37		6 3	6 77	20	9 N	A		3.8	2			
10/8/97	33		8 3	4 70	19	0 N	Α						
10/9/97	N.			A NA	A N	A N	AÎ						
10/10/97			4 3	0 7	1 16	6 N	A		2,8	5			
10/11/97			Al N			A N	Α						
10/12/97			A N	A NA	À N	A N	A						
10/13/97			2 3	3 8:	2 18	32 N	A						
10/14/97				8 5	6 14	15 N	A		3.0	3			
10/15/97				6 5	9 16	6 N	A					<u></u>	
10/16/97				0 5	6 18	32 N	Α						
10/17/97				9 7		22 N	Α		3.6	6			
10/18/97				A N		IA N	Α						
10/19/97				A N	Al N	IA N	Α		2.8	30		<u> </u>	
10/19/97							IA						
10/21/97							ΙΑ		2.1	30			
10/22/97							IA						
10/22/97							IA						
10/23/97							IA		2.	32			
10/24/97	_			IA N			IA I			\neg			
10/25/97				IA N	_		IA	_					
1 111/75/U/		`ا تحمد	v— ()	- (N									

TABLE 2
SUMMARY OF ZINC CONCENTRATIONS (MG/L)
GROUNDWATER RECOVERY SYSTEM PERFORMANCE REPORT - NOVEMBER 1997
MADISON INDUSTRIES, INC.

						WATER		NITORIN VATION		sui	RFACE WA	(ER
DATE		RECOVER		1411		TREAT.		X-7	MI-9	D-1	D-2	D-3
SAMPLED	RS-1A	RS-1B	RS-1C	RS-10	AVG.	COMP.	X-8	A-1	3.36		<u> </u>	
10/28/97	287	227	26	63	151	NA			0.00	1.8	24.3	7.2
10/29/97	282	228	32	55	149							
10/30/97	272	290	29	84	169				2.82			
10/31/97	297	291	31	77	174				2.02	·~		
11/1/97	NA	ŅA	NA	NA	NA NA							
11/2/97	NA	NA	NA	NA	NA							
11/3/97	293	209	29	66	149				6.2			1
11/4/97	313	299	33	68	178	+			0.2		 	
11/5/97	307	250		70	164	+					 	
11/6/97	372	324	34	106	209	+			3.17		 	-
11/7/97	326	271	30	68	174				3.17	 	 	
11/8/97	N/A	NA NA	NA	NA	N/							
11/9/97	N/	NA	NA NA	NA	N/					 	+	┼──
11/10/97	327	303	30	99	190				4.00	.	 	+
11/11/97	308	300	32	64	170				4.02		-	+
11/12/97	360	322	34	66	19				 		 	+
11/13/97	254	232	26	70	14				1 4 4 6	,	+	+
11/14/97	42	7 393	40	90	23				4.18	' 	+	+
11/15/97	N/	NA NA	N/	NA NA	N/					 	+	+
11/16/97	N/	A NA	N/	NA NA	N.				<u> </u>		 	
11/17/97	34	8 314	1 32		19				2.5	1		
11/18/97	30	5 216	3 22	73	15				2.5	11		
11/19/97	38	0 30	7 33	78	19				<u> </u>		<u> </u>	
11/20/97	35	7 26	26	72	18				<u> </u>	<u> </u>	 -	 -
11/21/97	32	9 23	5 29	81	16			ļ	2.7	4		
11/22/97	N.	A N	A N	AN A	N N	A NA	<u> </u>	<u> </u>		 		
11/23/97	N	A N	A N	A NA	<u> N</u>	A NA						+
11/24/97	35	0 33	6 34	84	20	1 NA	<u> </u>	ļ	2.6	1		
11/25/97	39	4 35	2 38	73	21	4 NA	<u> </u>	<u> </u>	ļ			
11/26/97	35	8 27	4 30	68				ļ		_		
11/27/97	N	A N	A N	A NA	N N	IA NA	`					
11/28/97	N	A N	Al N	A NA	1 1	IA NA	\					
11/29/97	N	A N	A N	A NA	1 1	IA NA		ļ				
11/30/97		A N	A N	A NA	1 1	IA NA		ļ				
12/1/97		IA N	A N	A NA		IA NA						
12/2/97		IA N	A N	A N	1 /	IA N					1	_
12/3/97	25	57 16	5 1	7 66	1:	26 NA					0 19	
MINIMUM		9 16	5 1	7 5	5 1	26 9			_			.6
MAXIMUN		0 163	186	0 121	0 14						.5 34	
AVERAGE		75 61		3 19	5 3	99 42	4 874.5	658.	5 70.4	11 1	.1 16	.4 10

NOTES:

N/A - Not Applicable (sampling/analysis not conducted)

All analysis performed by Madison Industries, Inc.

All concentrations in milligrams per liter (mg/l)

TABLE 3 SUMMARY OF ZINC CONCENTRATIONS FOR SELECTED WELLS AND SURFACE WATER (MG/L) PERFORMANCE MONITORING PERIOD RESULTS **GROUNDWATER RECOVERY SYSTEM PERFORMANCE REPORT - NOVEMBER 1997** MADISON INDUSTRIES, INC.

e de la companya de l	WELL					PMP PEF	RIOD						440 07
SAMPLE I.D.	DEPTH (S/D)	NO. 16 12/94	NO. 17 3/95	NO. 18 6/95	NO. 19 9/95	NO. 20 12/95	NO, 21 3/96	NO. 22 6/96	NO. 23 9/96	NO, 24 12/96	NO. 25 3/97	NO. 26 6/97	NO. 27 9/97
		81.00	2.00	46.00	105.00	256.00	324.00	1040.00 *	1070.00	NA	3.70	3.52	4,18
MI-2A	<u> </u>		7.00	5.80	5.80 4	7.60 4	7.00	4,00	5.40	5.40 *	4.30	3.15	4.49
MI-7	<u> </u>	8.10		NA NA	NA NA	NA NA	NA	NA NA	NA	NA	NA	20.90	4.55
MI-9	<u>S</u>	NA NA	NA		2.70	2,90	2.65	2.30	2.40	2.30	2.10	2.18	2.06
MI-T1	s	2.90	6.00	3.80		2.50 NA	NA NA	NA NA	NA	NA	NA	557.00 *	313.00
RS-1A	S	NA	NA	NA NA	NA		NA NA	NA NA	NA NA	NA	NA	639.00	398.00
RS-1B	S	NA NA	NA	NA	NA	NA	NA NA	NA NA	NA NA	NA NA	NA	93.60	44.10
RS-1C	S	NA NA	NA	NA	NA	NA		NA NA	NA NA	NA NA	NA	155.00	79.90
RS-1D	s	NA NA	NA NA	NA	NA_	NA NA	NA NA	 	2.30	1.50	1.50	1.20	1.20
RW-2	S	1.70	1.50	2.00	3, 10	2.35	3.00	2.60		30.00	26.50	2.13	0.81
RW-4	Ð	74.00	49.00	96.00 4	71.00	96.00	66.00 4	42.00	41.50		14.00	7.75	7.01
RVV-6	s	460.00	160.00	288.00	272.00	288.00	392.00	500.00 *	56.00	180.00	14.70	1.80	0.83
WCC TIM	D	72.00	80.00 4	188.00 4	176.00 4	52,00 .4	164.00 *	120.00 *	38.50	22.80		0.60	1.10
WCC-12	D	0.68	1.40	3.40	1.40	0.65	0.32	0.78	0.42	1.09	0.53		5.05
WCC-15M	Ð	20.00 4	6.80 4	11.00 4	3.80	2.25	2.80	35.60 *	43.00 *	15.40 *	5.55	5.53	4.87
WCC-16VS	S	11.00	12.00 '	13.50 4	16.60	44.00	15.50 4	14.80	11.80 *	4.60	3.54	4.92	
SW-2	AII	35.00	2.00	NA	NA	NA	3.60	470.00	415.00	18.20	34.40	22.70	28.30

NOTES:

S - Designated as a shallow well (< 40 feet in depth)

D - Designated as a deep well (> 40 feet in depth)

All analyses performed or subcontracted by CORE LABORATORIES (N.J. Certification No.: 12010)


mg/l - Milligrams per liter

Blank - flot detected (below Method Detection Limit of .030 mg/l)

IIA - Not Applicable/Not Available

MI-2A replaced MI-2 beginning PMP No. 25

* Exceeds NJ Class II groundwater criteria or POL, as appropriate; NA for SW samples.



GENERAL NOTES:

GENERAL LAYOUT DERIVED FROM DRAWINGS PREPARED BY CONCEPT ENGINEERING CONSULTANTS. P A

SOME LOCATIONS AND DETAIL APPROXIMATE

SCALE BY FEET

MI 2A
16 19 SHALLOW MONITORING WELL
GHOLINDWATER ELEVATION (FT ABOVE MSL)

RS 1A SHALLOW RECOVERY WELL
(DATA NOT IISED IN CONTOUR CALCULATIONS)

— 16 — ESTIMATED GROUNDWATER ELEVATION
CONTOUR (FT ABOVE MSL)

BUILDING OR STRUCTURE

SURFACE WATER SAMPLING LOCATION


Madison ... industries inc.

GROUNDWATER LEVEL CONTOUR MAP NOVEMBER 24, 1997

GROUNDWATER RECOVERY SYSTEM PERFORMANCE REPORT

FIGURE

FIGURE 2 - AVERAGE ZINC CONCENTRATIONS -- RS-1



DATE

FIGURE 3 - ZINC CONCENTRATIONS RS-1A AND RS-1B





FIGURE 4 - ZINC CONCENTRATIONS RS-1A AND RS-1B JULY 1, 1997 THROUGH DECEMBER 3, 1997



RS-1A
RS-1B
Linear (RS-1A)
Linear (RS-1B)

FIGURE 5 - ZINC CONCENTRAIONS RS-1C AND RS-1D




FIGURE 6 - ZINC CONCENTRATIONS RS-1C AND RS-1D JULY 1, 1997 THROUGH DECEMBER 3, 1997




FIGURE 7 - ZINC CONCENTRATIONS -- SELECTED WELLS PERFORMANCE MONITORING PROGRAM RESULTS




FIGURE 8 - ZINC CONCENTRATIONS -- SURFACE WATER

